



State of Rhode Island
Department of Transportation

Underwater Inspection of

Bridge Nos. 020001 & 020021

**Washington Bridge South & Washington Bridge South
Pedestrian**

Interstate 195 Eastbound & Bike Path/Pedestrian Bridge

Over

Seekonk River

In

East Providence, Rhode Island



July 23, 2021

Prepared by:

Jacobs

Underwater Inspection Report

Bridge Nos.: 020001 & 020021 Inspection Date: 7/23/2021
 Bridge Names: Washington Bridge South & Washington Bridge South Pedestrian
 Facility Carried: Interstate 195 Eastbound & Bike Path/Pedestrian
 Feature Intersected: Seekonk River
 City/Town: East Providence

Table of Contents

<u>Report Sections</u>	<u>Sheet Number(s)</u>
Cover Sheet	1
Table of Contents	2
Bridge Inventory and Inspection Information	3
Summary of Findings	4
Item 60 - Abutments	5 - 6
Item 60 - Piers	7 - 13
Item 61 - Channel and Channel Protection	14 - 15
Drawings / Sketches	F1-F6
Photos	P1-P26

Underwater Inspection Report

Bridge Nos.: 020001 & 020021 Inspection Date: 7/23/2021
 Bridge Names: Washington Bridge South & Washington Bridge South Pedestrian
 Facility Carried: Interstate 195 Eastbound & Bike Path/Pedestrian
 Feature Intersected: Seekonk River
 City/Town: East Providence

Bridge Inventory Information

Bridge Types: Steel multi-girder (Interstate 195 Eastbound) and reinforced concrete open
 spandrel arch (bikepath / pedestrian bridge)
 Year Built / Rebuilt: 1930 / 2008
 Bridge Orientation: Bridge is logged from west to east which is consistent with the previous NBIS
 inspection report and the structure plans.
 Structure Length: 1670.4 feet
 Width Out-to-Out: 71.5 feet
 No. of Span(s): 14
 No. of Pier(s): 13
 No. of Abutment(s) in Water: 0
 No. of Pier(s) in Water: 6
 Abutment / Pier Type: The pier walls are reinforced concrete with stone facing.
 Foundation Type: The pier walls are founded on reinforced concrete pile caps with timber
 piles.

Waterway Information

Type of Water: Brackish (Tidal)
 Current Strength: Approximately 1.5 feet/second
 Underwater Visibility: Approximately 4 feet
 Max. Water Depth: 31.4 feet
 Max. Depth at substructure: 30.5 feet (south nose of
 Pier 5)
 Bottom Composition: The channel bottom consists of silt, sand, and shells with scattered
 construction debris throughout. The maximum penetration into the channel
 bottom is 12".
 Marine Growth: There is marine growth up to 1/2" thick on the piers, most notably beneath
 the tidal zone.

Inspection / Diving Operations

Inspection Team Leader: Ryan Breen, P.E.
 Inspection Team Members / Divers: Matthew Dwyer, P.E. and Benjamin Sheppard (Dive Sup.)
 Inspection Date Started: 6/21/2021
 Inspection Date Completed: 7/23/2021
 Bridge Access: Boat (launched from Bold Point Park, southeast of the bridge)
 Boat Size: 20 foot
 Dive Mode: Surface-Supplied Air Diving with Dive
 Helmets & Hardwire Communications
 Equipment Comments: Standard hand tools were used for this inspection.
 General Remarks: Soundings performed on 6/22/2021.

Underwater Inspection Report

Bridge Nos.: 020001 & 020021 Inspection Date: 7/23/2021
Bridge Names: Washington Bridge South & Washington Bridge South Pedestrian
Facility Carried: Interstate 195 Eastbound & Bike Path/Pedestrian
Feature Intersected: Seekonk River
City/Town: East Providence

Summary of Findings

Item 60 - Substructure

Overall Rating: 6 - Satisfactory

At Piers #4 through #9, the steel encased reinforced concrete caisson pile at the north (upstream) end of the piers exhibits minor corrosion below the fiberglass jackets. At Piers #4 through #7 and #9, the stone masonry facade exhibits less than 5% deteriorated mortar with 3" to 6" of penetration between stones and isolated full-height cracked stones. Pier #8 has 15% deteriorated mortar with up to 6" of penetration between stones. The reinforced concrete stem below the stone masonry facade has abrasion 1/2" deep. Piers #4, #7 and #9 have cracks up to full height and open 1/4" to 1/2" wide. At Piers #4, #5 and #8, the steps / pile caps have been exposed up to 4.5' vertically and the seal has become exposed at the south end of Pier 8 with up to 15" of vertical exposure.

Item 61 - Channel & Channel Protection

Overall Rating: 6 - Satisfactory

The channel bottom consists of silt, sand, and shells with scattered construction debris throughout. The maximum penetration into the channel bottom is 12". There has been no apparent change to the channel orientation as compared to the 2017 Underwater Inspection Report. No erosion was observed along the channel embankments. There is construction debris consisting of concrete rubble and cut-off timber piles at the channel bottom adjacent to the piers. There is no significant obstructions or debris accumulation which would affect the hydraulic opening at the bridge.

The timber fender system members exhibit minor splits and checking. The newer navigational lighting system in did not have lights on at the time of the inspection.

Item 113 - Scour Critical

Overall Rating: 3 - Unstable

As compared to the 2017 Underwater Inspection Report, there is full height pile cap exposure with up to 15" of vertical seal exposure at the south end of Pier 8, pile cap at Pier 9 has become exposed with up to 4.5' of vertical exposure, and the pile caps at Piers #4, #5 remain exposed. A scour analysis was performed to evaluate the scour potential at the bridge site. Based on this scour analysis, the structure has been rated a "3" or "Unstable".

General Condition Rating for Evaluating the Condition of Substructure & Channel Components

NOTE: Condition ratings are assigned in accordance with the National Bridge Inspection Standards (NBIS) coding information, as presented in the Federal Highway Administration Report No. FHWA-PD-96-001 "Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges," dated December 1995 (revised March 11, 2004).



Underwater Inspection Report

Bridge Nos.: 020001 & 020021 Inspection Date: 7/23/2021
 Bridge Names: Washington Bridge South & Washington Bridge South Pedestrian
 Facility Carried: Interstate 195 Eastbound & Bike Path/Pedestrian
 Feature Intersected: Seekonk River
 City/Town: East Providence

Item 60 - Substructure

Abutment No.: 1 **Overall Rating:** NA

Component	Rating	Description
STEM	7	The abutment is located out of the water and therefore was not inspected as part of this underwater inspection. Rating is based on the 2021 NBIS Inspection Report.
FOOTING	N	
EROSION	N	Erosion was not evaluated along the abutment.
SETTLEMENT	N	The abutment is located out of the water and therefore was not inspected as part of this underwater inspection.
SCOUR	N	
WINGWALLS	7	The return walls are located out of the water and therefore were not inspected as part of this underwater inspection. Rating shall be based on the 2021 NBIS Inspection Report.

General Condition Rating for Evaluating the Condition of Substructure Components

NOTE: Condition ratings are assigned in accordance with the National Bridge Inspection Standards (NBIS) coding information, as presented in the Federal Highway Administration Report No. FHWA-PD-96-001 "Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges," dated December 1995 (revised March 11, 2004).

Underwater Inspection Report

Bridge Nos.: 020001 & 020021 Inspection Date: 7/23/2021
 Bridge Names: Washington Bridge South & Washington Bridge South Pedestrian
 Facility Carried: Interstate 195 Eastbound & Bike Path/Pedestrian
 Feature Intersected: Seekonk River
 City/Town: East Providence

Item 60 - Substructure

Abutment No.: 2 **Overall Rating:** NA

Component	Rating	Description
STEM	7	The abutment is located out of the water and therefore was not inspected as part of this underwater inspection. Rating is based on the 2021 NBIS Inspection Report.
FOOTING	N	
EROSION	N	Erosion was not evaluated along the abutment.
SETTLEMENT	N	The abutment is located out of the water and therefore was not inspected as part of this underwater inspection.
SCOUR	N	
WINGWALLS	7	The return walls are located out of the water and therefore was not inspected as part of this underwater inspection. Rating is based on the 2021 NBIS Inspection Report.

General Condition Rating for Evaluating the Condition of Substructure Components

NOTE: Condition ratings are assigned in accordance with the National Bridge Inspection Standards (NBIS) coding information, as presented in the Federal Highway Administration Report No. FHWA-PD-96-001 "Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges," dated December 1995 (revised March 11, 2004).

Underwater Inspection Report

Bridge Nos.: 020001 & 020021 Inspection Date: 7/23/2021
 Bridge Names: Washington Bridge South & Washington Bridge South Pedestrian
 Facility Carried: Interstate 195 Eastbound & Bike Path/Pedestrian
 Feature Intersected: Seekonk River
 City/Town: East Providence

Item 60 - Substructure

Pier/Bent Nos.: 1 - 3 & 10 - 13

Overall Rating: NA

Component	Rating	Description
PILES	7	The caisson piles at the north (upstream) ends of the piers are located out of the water and therefore were not inspected as part of this underwater inspection. Rating shall be based on the 2021 NBIS Inspection Report.
STEM	7	The piers are located out of the water and therefore were not inspected as part of this underwater inspection. Rating shall be based on the 2021 NBIS Inspection Report.
FOOTING	N	
SCOUR	N	
SETTLEMENT	N	The piers are located out of the water and therefore were not inspected as part of this underwater inspection.

General Condition Rating for Evaluating the Condition of Substructure Components

NOTE: Condition ratings are assigned in accordance with the National Bridge Inspection Standards (NBIS) coding information, as presented in the Federal Highway Administration Report No. FHWA-PD-96-001 "Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges," dated December 1995 (revised March 11, 2004).



State of Rhode Island
Department of Transportation


Bridge Nos. 020001 & 020021

**Washington Bridge South
& Bike Path / Pedestrian Bridge**

Drawings / Sketches

Prepared by:

Jacobs



GENERAL NOTE:


1. AT THE TIME OF INSPECTION ON 6/7/2017, THE WATERLINE WAS LOCATED BETWEEN 6.0 AND 10.0 FT BELOW THE TOP OF THE STONE FACING AT THE UPSTREAM (NORTH) NOSE OF PIERS #1-#10 (DATUM ELEVATION 0.0).
2. AT THE TIME OF INSPECTION ON 6/22/2021 THE WATERLINE WAS LOCATED BETWEEN 5.5 AND 9.0 FT BELOW THE TOP OF THE STONE FACING AT THE UPSTREAM (NORTH) NOSE OF PIERS #1-#10 (Datum Elevation 0.0).
3. SOUNDINGS ACROSS THE CHANNEL WERE TAKEN PARALLEL TO THE BRIDGE IMMEDIATELY ADJACENT TO 5 FT OFF AND 10 FT OFF THE PILE CAP AND TREMIE SEAL AT THE PIERS AS WELL AS AT THE QUARTER POINTS AND MIDPOINT OF EACH SPAN AT THE BRIDGE FASCIAS, AND ARE ACTUAL DISTANCES FROM THE ASSIGNED DATUM IN FEET.
4. SOUNDINGS PARALLEL TO THE SUBSTRUCTURE WERE TAKEN AT 5 FT INTERVALS IMMEDIATELY ADJACENT TO 5 FT OFF AND 10 FT OFF THE PILE CAP AND TREMIE SEAL AT THE PIERS AS WELL AS BOTH PIER NOSES AND ARE ACTUAL DISTANCES FROM THE ASSIGNED DATUM IN FEET.
5. VARIATIONS BETWEEN THE 2017 AND 2013 CHANNEL BOTTOM PROFILES ARE LIKELY DUE TO THE SOFT COMPOSITION OF THE CHANNEL BOTTOM AT CERTAIN LOCATIONS.
6. THIS FIGURE WAS DEVELOPED FROM FIELD NOTES, SKETCHES AND STRUCTURE PLANS.

LEGEND

2021
2017

CHANNEL BOTTOM DEPTHS FROM DATUM PARALLEL TO STRUCTURE ALONG THE UPSTREAM AND DOWNSTREAM FASCIAS AND ALONG PIER FASCIA

JACOBS	DESIGNED BY	EAST PROVIDENCE, RHODE ISLAND INTERSTATE 195 EASTBOUND & BIKE PATH/PEDESTRIAN BRIDGE OVER SEEKONK RIVER	SCALE	REVISION
	DRAWN BY		N.T.S.	
	CHECKED BY		DATE	
	PROJECT ENGR		8/20/2021	
BRIDGE NO. 020001 & 020021		SOUNDING PLAN	DRAWING NO. FIG. 1	



SOUNDING PLAN

GENERAL NOTE:

1. AT THE TIME OF INSPECTION ON 6/7/2017, THE WATERLINE WAS LOCATED BETWEEN 6.0 AND 10.0 FT BELOW THE TOP OF THE STONE FACING AT THE UPSTREAM (NORTH) NOSE OF PIERS #1-#10 (DATUM ELEVATION 0.0).
2. AT THE TIME OF INSPECTION ON 6/22/2021 THE WATERLINE WAS LOCATED BETWEEN 5.5 AND 9.0 FT BELOW THE TOP OF THE STONE FACING AT THE UPSTREAM (NORTH) NOSE OF PIERS #1-#10 (Datum Elevation 0.0).
3. SOUNDINGS ACROSS THE CHANNEL WERE TAKEN PARALLEL TO THE BRIDGE IMMEDIATELY ADJACENT TO 5 FT OFF AND 10 FT OFF THE PILE CAP AND TREMIE SEAL AT THE PIERS AS WELL AS AT THE QUARTER POINTS AND MIDPOINT OF EACH SPAN AT THE BRIDGE FASCIAS, AND ARE ACTUAL DISTANCES FROM THE ASSIGNED DATUM IN FEET.
4. SOUNDINGS PARALLEL TO THE SUBSTRUCTURE WERE TAKEN AT 10 FT INTERVALS IMMEDIATELY ADJACENT TO 5 FT OFF AND 10 FT OFF THE PILE CAP AND TREMIE SEAL AT THE PIERS AS WELL AS BOTH PIER NOSES AND ARE ACTUAL DISTANCES FROM THE ASSIGNED DATUM IN FEET.
5. VARIATIONS BETWEEN THE 2017 AND 2021 CHANNEL BOTTOM PROFILES ARE LIKELY DUE TO THE SOFT COMPOSITION OF THE CHANNEL BOTTOM AT CERTAIN LOCATIONS.
6. THIS FIGURE WAS DEVELOPED FROM FIELD NOTES, SKETCHES AND STRUCTURE PLANS.


LEGEND

2021 CHANNEL BOTTOM DEPTHS FROM DATUM PARALLEL TO STRUCTURE ALONG THE UPSTREAM AND DOWNSTREAM FASCIAS AND ALONG PIER FASCIA
2017

JACOBS	DESIGNED BY	EAST PROVIDENCE, RHODE ISLAND INTERSTATE 195 EASTBOUND & BIKE PATH/PEDESTRIAN BRIDGE OVER SEEKONK RIVER	SCALE	REVISION
	DRAWN BY		N.T.S.	
	CHECKED BY		DATE	
	PROJECT ENGR		06/07/2021	
BRIDGE NO. 020001 & 020021		DRAWING NO.		
SOUNDING PLAN		FIG. 2		

INSPECTION NOTE:


- ① AT PIERS 4, 5, & 6 THE CAISSON PILE AT THE NORTH (UPSTREAM) END OF THE PIER EXHIBITS MINOR CORROSION WITH LIGHT PITTING UP TO 1/16" DEEP ON THE EXPOSED PORTIONS OF THE STEEL CASING. THE FIBERGLASS WRAP EXTENDS 8 TO 10 FEET DOWN FROM THE UNDERSIDE OF THE CONCRETE CAP.
- ② AT PIERS 4, 5, & 6 THE STONE MASONRY EXHIBITS LESS THAN 5% DETERIORATED MORTAR WITH 3" TO 6" OF PENETRATION BETWEEN STONES.
- ③ THE EXPOSED SURFACES OF THE REINFORCED CONCRETE STEP/PILE CAP EXHIBIT ABRASION UP TO 1/2" DEEP.
- ④ THE CHANNEL BOTTOM CONSISTS OF SILT, SAND, SHELLS, AND SCATTERED CONSTRUCTION DEBRIS WITH UP TO 12" OF PROBE ROD PENETRATION.
- ⑤ AT PIER 4, THERE IS A FULL HEIGHT CRACK UP TO 1/4" WIDE THAT EXTENDS TO CHANNEL BOTTOM NEAR THE MIDPOINT ON THE WEST FACE.
- ⑥ AT PIER 4, THERE IS A CRACKED STONE BELOW WATER, 1/4" WIDE x FULL HEIGHT, IN THE FOURTH STONE COURSE NEAR THE SOUTH END ON THE EAST FACE OF THE PIER.
- ⑦ AT PIER 4, THE REINFORCED CONCRETE STEP/PILE CAP IS EXPOSED UP TO 2' VERTICALLY FROM THE NORTHEAST SHOULDER AND ALONG THE ENTIRE EAST FACE WITH MAXIMUM EXPOSURE AT THE SOUTHEAST SHOULDER.
- ⑧ AT PIERS 5 & 6, THERE IS ABRASION UP TO 1/2" DEEP ON THE REINFORCED CONCRETE PIER SHAFT BELOW THE STONE MASONRY.
- ⑨ AT PIER 5, THERE IS A BAND OF SCALING ON THE SOUTH NOSE NEAR THE CHANNEL BOTTOM THAT MEASURES FULL WIDTH x 3' HIGH x UP TO 3/4" PENETRATION.
- ⑩ AT PIER 5, THE REINFORCED CONCRETE STEP/PILE CAP IS EXPOSED UP TO 6" VERTICALLY ALONG THE SOUTH NOSE AND 4' ALONG THE WEST FACE.
- ⑪ AT PIER 5, THERE IS INTERMITTENT CONCRETE RUBBLE UP TO 2' IN DIAMETER ALONG THE FULL LENGTH OF THE EAST FACE OF THE PIER.
- ⑫ AT PIER 6, THERE IS MISSING MASONRY STONE AT THE MIDPOINT OF THE EAST FACE 2' LONG x 2.5' HIGH.
- ⑬ AT PIER 6, THERE ARE VOIDS AT THE CONCRETE/GRANITE INTERFACE MEASURING UP TO 3' LONG x 6" HIGH x 6" DEEP ALONG THE SOUTH AND WEST FACES OF THE PIER.
- ⑭ AT PIER 6, THERE IS A TIMBER PILE CUT OFF AT 10 FEET ABOVE CHANNEL BOTTOM AT THE NORTHEAST SHOULDER AND THREE TIMBER PILES LYING ON THE CHANNEL BOTTOM AT THE SOUTHEAST SHOULDER.
- ⑮ AT PIER 6, AT 15' NORTH OF THE SOUTHEAST CORNER THERE IS A 1/16" TO 1/8" WIDE VERTICAL CRACK ON THE EAST FACE THAT EXTENDS FROM THE 6TH MASONRY COURSE TO THE CHANNEL BOTTOM.
- ⑯ AT PIER 6, THE FIRST, THIRD, AND FOURTH MASONRY COURSES AT THE MIDPOINT ON THE WEST FACE EXHIBIT VERTICAL CRACKS UP TO 1/4" WIDE AND EXTENDING INTO THE CONCRETE FOOTING STEP 1/2" WIDE AT CHANNEL BOTTOM.
- ⑰ AT PIER 6, VERTICAL CRACK 1/16" WIDE IN 2nd MASONRY COURSE NEAR NORTH 1/4 POINT ON WEST FACE.
- ⑱ AT PIER 6, VERTICAL CRACK 1/8" WIDE IN 4th MASONRY COURSE NEAR THE MIDPOINT OF THE PEDESTRIAN BRIDGE ON WEST FACE.



INSPECTION PLAN

- ⑲ AT PIER 6, VERTICAL CRACK, HAIRLINE TO 1/4" WIDE IN TOP FOUR MASONRY COURSES NEAR MIDPOINT OF PEDESTRIAN BRIDGE ON EAST FACE.
- ⑳ AT PIER 6, VERTICAL CRACK IN TOP FOUR MASONRY COURSES BETWEEN PEDESTRIAN AND EASTBOUND BRIDGES ON EAST FACE THAT MEASURES 1/16" WIDE IN TOP MASONRY COURSE AND 1/4" WIDE IN 4th MASONRY COURSE.
- ㉑ AT PIER 6, INTERMITTENT BANDS OF POOR CONCRETE CONSOLIDATION ON ALL FACES OF CONCRETE PIER SHAFT BELOW MASONRY THAT MEASURE 6-12" HIGH AND 1/2" TO 1" DEEP.
- ㉒ THE TIMBER FENDER SYSTEM TOP WALE ALONG THE EAST SIDE OF THE PIER 6 EXHIBITS MINOR CHECKS AND SPLITS IN THE TIDAL ZONE AND THERE IS A FRACTURED HANDRAIL IN TWO LOCATIONS WITH ONE BROKEN POST.

JACOBS	DESIGNED BY	EAST PROVIDENCE, RHODE ISLAND INTERSTATE 195 EASTBOUND & BIKE PATH/PEDESTRIAN BRIDGE OVER SEEKONK RIVER	SCALE	REVISION
	DRAWN BY		N.T.S.	
	CHECKED BY		DATE	
	PROJECT ENGR		06/07/2021	
BRIDGE NO. 020001 & 020021		INSPECTION PLAN		DRAWING NO. FIG. 3




INSPECTION PLAN

INSPECTION NOTE:


- ① AT PIERS 7, 8, & 9, THE CAISSON PILE AT THE NORTH (UPSTREAM) END OF THE PIER EXHIBITS MINOR CORROSION WITH LIGHT PITTING UP TO 1/16" DEEP ON THE EXPOSED PORTIONS OF THE STEEL CASING. THE FIBERGLASS WRAP EXTENDS 8 TO 10 FEET DOWN FROM THE UNDERSIDE OF THE CONCRETE CAP.
- ② AT PIERS 7, & 9, THE STONE MASONRY EXHIBITS LESS THAN 5% DETERIORATED MORTAR WITH 3" TO 6" OF PENETRATION BETWEEN STONES.
- ③ AT PIER 8, THE STONE MASONRY EXHIBITS LESS THAN 15% DETERIORATED MORTAR WITH UP TO 6" OF PENETRATION BETWEEN STONES.
- ④ THE EXPOSED SURFACES OF THE REINFORCED CONCRETE STEP/PILE CAP EXHIBIT ABRASION UP TO 2" DEEP.
- ⑤ THE CHANNEL BOTTOM CONSISTS OF SILT, SAND, SHELLS, AND SCATTERED CONSTRUCTION DEBRIS WITH UP TO 12" OF PROBE ROD PENETRATION.
- ⑥ AT PIER 7, THERE IS 2" DEEP SCALING ON THE WEST FACE OF THE REINFORCED CONCRETE PIER SHAFT BELOW THE STONE MASONRY.
- ⑦ AT PIER 7, ISOLATED AREAS OF CONCRETE SCALING/SECTION LOSS NEAR THE CHANNEL BOTTOM:
 - a. 2' HIGH x 3" DEEP ON WEST FACE FROM NORTHWEST CORNER TO 25' SOUTH
 - b. 1' HIGH x 3.5" DEEP ON NORTH FACE FROM NORTHWEST CORNER TO MIDPOINT
 - c. ALONG NORTHEAST CORNER 13' HIGH x 5' WIDE x 2" DEEP
 - d. 6' HIGH x 2.5" DEEP ON EAST FACE NEAR SOUTH QUARTER-POINT
 - e. 4" HIGH x 3' LONG x 3" DEEP ON EAST FACE NEAR SOUTHEAST CORNER
 - f. 4' HIGH x 2.5" DEEP ALONG SOUTH FACE AT CHANNEL BOTTOM
 - g. ALONG SOUTHWEST CORNER 16.5' HIGH x 2' WIDE x UP TO 5" DEEP AT CHANNEL BOTTOM

- ⑧ AT PIER 7, SPALL IN TOP OF REINFORCED CONCRETE AT CABLE LOCATION ON EAST FACE AT 3' FROM SOUTHEAST CORNER THAT MEASURES 4" HIGH x 20" WIDE x 3" DEEP.
- ⑨ AT PIER 7, VERTICAL CRACKS 1/8" TO 1/4" WIDE THAT EXTEND FROM THE TOP DOWN TO THE CHANNEL BOTTOM NEAR THE MIDPOINTS ON THE EAST AND WEST FACES. ON THE EAST FACE THE CRACK IS UP TO 1/2" WIDE AT THE 4th MASONRY COURSE AND THERE IS SECTION LOSS WITH SOFT CONCRETE IN THE AREA OF THE CRACK 14" WIDE x 24" HIGH x 2.5" DEEP. WEST FACE EXHIBITS SECTION LOSS ALONG CRACK FROM CHANNEL BOTTOM UP 8.5' x 5" WIDE x 3" DEEP.
- ⑩ AT PIER 7, THE STONES IN THE FIRST AND SECOND MASONRY COURSES ARE BROKEN WITH 3.5' LONG x 5' HIGH SECTIONS OF STONE MISSING ON THE WEST FACE OF THE PIER.
- ⑪ AT PIER 7, THERE IS A STONE REVETMENT ALONG THE EAST FACE FROM THE NORTHEAST CORNER TO THE MIDPOINT OF THE PIER.
- ⑫ AT PIER 8, THERE IS A VOID IN THE CONCRETE STEP/PILE CAP 2' LONG x 8" HIGH x 5" DEEP AT THE SOUTH END OF THE EAST FACE OF THE PIER.
- ⑬ AT PIER 8, THE CONCRETE STEP/PILE CAP IS EXPOSED AROUND THE PIER NOSES AND INTERMITTENTLY ALONG THE PIER FACES WITH UP TO 4.5' VERTICAL EXPOSURE AT THE NORTHEAST CORNER. AT THE SOUTH NOSE THE CONCRETE STEP/PILE CAP IS FULLY EXPOSED, AND THE SEAL IS ALSO EXPOSED WHICH EXTENDS 2' WIDER WITH UP TO 15" OF VERTICAL EXPOSURE AND SOFT LATENT CONCRETE.
- ⑭ AT PIER 8, THERE ARE TWO TIMBER PILES PROTRUDING UP THROUGH THE CONCRETE PILE CAP WITH 12" EXPOSED ON THE SOUTH FACE AT 10' AND 15' FROM THE SOUTHEAST CORNER. THE TIMBER PILES AT ARE 60% AND 25% NON-BEARING AND EXHIBIT 15% AND 20% SECTION LOSS, RESPECTIVELY.
- ⑮ AT PIER 8, AREA OF SECTION LOSS ON THE CONCRETE STEP/PILE CAP AT THE SOUTHEAST CORNER THAT MEASURES 2' LONG x 8" HIGH x 5" DEEP.
- ⑯ AT PIER 8, THERE IS A VERTICAL CRACK IN THE TOP TWO STONE COURSES BELOW THE CAP UP TO 1/2" WIDE. THE CRACK ALSO EXTENDS THROUGH THE CONCRETE STEP/PILE CAP ON BOTH FACES UP TO 1/4" WIDE.
- ⑰ AT PIER 8, THERE IS 50% MORTAR LOSS IN THE JOINT AT THE MASONRY/CONCRETE INTERFACE.
- ⑱ AT PIER 9, THE CONCRETE STEP/PILE CAP IS EXPOSED ALONG THE WEST FACE FROM 6' SOUTH OF THE NORTHWEST CORNER TO 18' NORTH OF THE SOUTHWEST CORNER WITH UP TO 4.5' OF VERTICAL EXPOSURE AND AREAS OF POOR CONSOLIDATION/SECTION LOSS UP TO 2" DEEP.
- ⑲ AT PIER 9, THERE IS A 1/2" WIDE CRACK THROUGH THE FIRST THREE STONE COURSES NEAR THE MIDPOINT ON THE WEST FACE OF THE PIER. THE CRACK ALSO EXTENDS THROUGH THE CONCRETE STEP/PILE CAP TO THE CHANNEL BOTTOM.
- ⑳ THE FENDER SYSTEM MEMBERS ALONG THE WEST SIDE OF PIER 7 EXHIBIT MINOR CHECKS AND SPLITS IN THE TIDAL ZONE AND A MISSING SECTION OF HANDRAIL NEAR THE NORTH END OF THE PEDESTRIAN BRIDGE.
- ㉑ THERE ARE TWO ABANDONED TIMBER DOLPHINS IN SEVERE CONDITION ON THE SOUTH SIDE OF PIER 7. NEW TIMBER DOLPHINS HAVE BEEN CONSTRUCTED TO REPLACE THEM.

JACOBS	DESIGNED BY	EAST PROVIDENCE, RHODE ISLAND	SCALE	REVISION
	DRAWN BY	INTERSTATE 195 EASTBOUND & BIKE	N.T.S.	
	CHECKED BY	PATH/PEDESTRIAN BRIDGE OVER SEEKONK RIVER	DATE	
	PROJECT ENGR		06/07/2021	
		BRIDGE NO. 020001 & 020021	DRAWING NO.	
		INSPECTION PLAN	FIG. 4	



UPSTREAM FASCIA SOUNDING PLAN



DOWNSTREAM FASCIA SOUNDING PLAN


LEGEND

- CHANNEL BOTTOM PROFILE ON 6/7/2017
- CHANNEL BOTTOM PROFILE ON 2021


GENERAL NOTE:

1. AT THE TIME OF INSPECTION ON 4/21/2020, THE WATERLINE WAS MEASURED AS 15.3 FT. BELOW THE TOP OF THE PIER 6 CAP AT THE NORTH END. BASED ON THE TOP OF PIER CAP ELEVATIONS OF 862.9 FT., THE WATERLINE ELEVATION WAS 847.6 FT.
2. SOUNDING INDICATE THE CHANNEL BOTTOM DEPTHS AT THE TIME OF INSPECTION AND ARE MEASURED IN FEET.
3. THESE FIGURES WERE DEVELOPED FROM FIELD OBSERVATION AND BRIDGE PLANS DATED 2001.

JACOBS	DESIGNED BY	EAST PROVIDENCE, RHODE ISLAND INTERSTATE 195 EASTBOUND & BIKE PATH/PEDESTRIAN BRIDGE OVER SEEKONK RIVER BRIDGE NO. 020001 & 020021 UPSTREAM AND DOWNSTREAM FASCIA PROFILE	SCALE	REVISION
	DRAWN BY		N.T.S.	
	CHECKED BY		DATE	
	PROJECT ENGR		8/20/2021	DRAWING NO.
			FIG. 5	



UPSTREAM FASCIA SOUNDING PLAN



DOWNSTREAM FASCIA SOUNDING PLAN

LEGEND

- CHANNEL BOTTOM PROFILE ON 6/7/2017
- CHANNEL BOTTOM PROFILE ON 2021

GENERAL NOTE:

1. AT THE TIME OF INSPECTION ON 4/21/2020, THE WATERLINE WAS MEASURED AS 15.3 FT. BELOW THE TOP OF THE PIER 6 CAP AT THE NORTH END. BASED ON THE TOP OF PIER CAP ELEVATIONS OF 862.9 FT., THE WATERLINE ELEVATION WAS 847.6 FT.
2. SOUNDING INDICATE THE CHANNEL BOTTOM DEPTHS AT THE TIME OF INSPECTION AND ARE MEASURED IN FEET.
3. THESE FIGURES WERE DEVELOPED FROM FIELD OBSERVATION AND BRIDGE PLANS DATED 2001.

JACOBS	DESIGNED BY	EAST PROVIDENCE, RHODE ISLAND INTERSTATE 195 EASTBOUND & BIKE PATH/PEDESTRIAN BRIDGE OVER SEEKONK RIVER BRIDGE NO. 020001 & 020021 UPSTREAM AND DOWNSTREAM FASCIA PROFILE	SCALE	REVISION
	DRAWN BY		N.T.S.	
	CHECKED BY		DATE	
	PROJECT ENGR		8/20/2021	DRAWING NO.
			FIG. 6	



State of Rhode Island
Department of Transportation

Bridge Nos. 020001 & 020021


**Washington Bridge South
& Bike Path / Pedestrian Bridge**

Photos

Prepared by:

Jacobs

Photo #1



Pier 3

Pier 4


Pier 5

Pier 6

Bridge #020001 and 020021

Overall view of Piers 3 through 6, looking northwest.

7/23/2021



Pier 7

Pier 8

Pier 9



Photo #4



Bridge #020001 and 020021

West shoreline south of bridges, looking west.

7/23/2021

Photo #5



Bridge #020001 and 020021

East face of Pier 4, looking southwest.

7/23/2021



Photo #7



Vertical crack
in stone

Bridge #020001 and 020021

View of west face of Pier 4, looking northeast.

7/23/2021



Photo #9



Bridge #020001 and 020021

East face of Pier 5, looking southwest.

7/23/2021

Photo #10



Bridge #020001 and 020021

View of Pier 5 Caisson, looking east.

7/23/2021

Photo #11



Bridge #020001 and 020021

West face of Pier 6, looking northeast.

7/23/2021

Photo #12



Bridge #020001 and 020021

View of Pier 6 Caisson and north face, looking east.

7/23/2021



Vertical cracks
in stone

Photo #14



Vertical crack
below water

Bridge #020001 and 020021

West face of Pier 6 near midpoint, looking east.

7/23/2021



Photo #16



Bridge #020001 and 020021

North portion of Pier 7 and Caisson, looking west.

7/23/2021

Photo #17



Vertical cracks
to stone

Bridge #020001 and 020021

East face of Pier 7 near midpoint, looking northwest.

7/23/2021

Photo #18



Missing/broken
stones

Bridge #020001 and 020021

West face of Pier 7 near midpoint, looking east.

7/23/2021

Photo #19



Bridge #020001 and 020021

South portion of Pier 8, looking east.

7/23/2021

Photo #20



Bridge #020001 and 020021

North portion of Pier 8 and Caisson, looking northeast.

7/23/2021

Photo #21



Vertical crack
to stone

Bridge #020001 and 020021

East face of Pier 8, looking west.

7/23/2021

Photo #22



Bridge #020001 and 020021

South portion of Pier 9, looking east.

7/23/2021



Photo #24



Vertical crack
in stones

Bridge #020001 and 020021

West face of Pier 9, looking east.

7/23/2021



